

Inspection Photos

API: 071-09919

Operator: TWIN BRIDGES RESOURCES LLC

Inspection Date: 5/31/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 1. Facing northwest near the location. Equipment is being stored near the location. All equipment will need to be removed and disturbance reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 2. Facing southeast at the entrance of the access road. Sign is posted at entrance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 3. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 4. The well has been drilled at the location. The wellhead cellar (yellow arrow) needs to be covered to prevent entry. There is oil stained soils (red arrow) that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 5. The down gradient straw wattles are not installed correctly. There is a gap between the ends of the wattles and there is no staking to hold them in place.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 6. The disturbed tree debris around the location will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 7. It is unknown which pile of material is the cuttings pile. It appears some cuttings is on the surface in photo. The wattles are not staked down around the pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022

Inspection Photos



Photo 8. There are a multiple soil piles around the location. The wattles are not staked down around the pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09919 | Date: 5/31/2022