

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 1 – Wellheads

Photo 2 – Wellheads

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 3 – Wellheads



Photo 4 – Label starting to weather

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 5 – Labels missing

Photo 6 – Gas Lift Injection Meter House

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 7 – Separators



Photo 8 – Separator

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 9 – Electrical and Instrument Air Units



Photo 10 – ECDs

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 11 – Tank Battery



**Photo 12 – Unused Containment – NOT covered with
Wildlife netting**

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 13 – LACT



Photo 14 – VRUs

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 15 – Gas Meter House



Photo 16 – Compressors

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 17 – Wildlife Netting is missing/disrepair

Photo 18 – Wildlife Netting is missing/disrepair

Inspection Photos
Location Name: Stampede Federal 8-60-4 PAD
Location ID: 455627



Photo 19 – Location Sign at Entrance