

Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314277

Location Name: Wilson Creek Unit-63N94W/34NWNW

Inspection Document #: 702800265

Rio Blanco County, CO

NWNW Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-63N94W/34NWNW

Location ID: 314277



Photo 1. Photo taken from the well area shows the excavated area around the well.



Photo 2. Refer to Photo 1 comment.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 702800265

Inspection Photos

Location Name: Wilson Creek Unit-63N94W/34NWNW

Location ID: 314277



Photo 3. Photo taken from the north of the Location shows a pile of soil which may be impacted by E&P waste stored without sufficient control measures to prevent sediment and E&P waste from migrating off site.



Photo 4. Photo taken from the west of the Location shows a soil berm at the edge of the Location intended as a temporary measure to prevent migration of E&P waste off site. The berm may act as a sediment source/stormwater pollutant.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800265