

Inspection Photos

API: 071-06435

Operator: OGRIS OPERATING LLC

Inspection Date: 6/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06435 | Date: 6/1/2022

Inspection Photos



Photo 1. Facing toward the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 6/1/2022

Inspection Photos



Photo 2. Facing northwest at the reclaimed access road in the canyon bottom. There are noxious weeds in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 6/1/2022

Inspection Photos



Photo 3. View of Scotch thistle found in canyon bottom along the reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 6/1/2022

Inspection Photos



Photo 4. Facing northeast along the reclaimed road. The perennial vegetation is progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06435 | Date: 6/1/2022