

Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314497

Location Name: Wilson Creek Unit-62N94W/2SWNE

Inspection Document #: 702800269

Rio Blanco County, CO

SWNE Section 2 T2N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



Photo 1. Photo taken from the well area shows the excavation around the wellhead. The slope of the sides is gentle enough to allow for wildlife egress. Fence panels are present around the entire excavated area.



Photo 2. Photo taken from the east of the Location shows a soil pile. A straw wattle has been added around the downslope perimeter of the pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800269

Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



Photo 3. Photo taken from the west of the Location shows a soil pile to the right. A straw wattle has been added around the downslope perimeter of the pile. Piles of soil from the Location are present downslope of the wattle and off site.



Photo 4. Photo taken from the west of the Location shows a soil pile from the Location present offsite. Soil continues down the hillside approximately 30 yards from the Location edge.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800269

Inspection Photos

Location Name: Wilson Creek Unit-62N94W/2SWNE

Location ID: 314497



Photo 5. Refer to Photo 4 comments.



Photo 6. Refer to Photo 4 comments.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800269