

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 1 – Signs at Entrance

Photo 2 – South Wellhead

**Inspection Photos**  
**Location Name: Hunt 8-60-17A PAD**  
**Location ID: 457131**



**Photo 3 – North Wellheads**



**Photo 4 – Unmarked Riser at West Separators – Marking has faded No Longer visible**

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131




Photo 5 – Screen has been installed

Photo 6 – Screen has been installed

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131




Photo 7 – Unmarked Risers NW of Separators

Photo 8 – Gas Meter Houses

**Inspection Photos**  
**Location Name: Hunt 8-60-17A PAD**  
**Location ID: 457131**



**Photo 9 – Compressors, VRUs, and ECDs**



**Photo 10 – Tank Battery**

**Inspection Photos**  
**Location Name: Hunt 8-60-17A PAD**  
**Location ID: 457131**



**Photo 11 – Tank Battery Sign**

**Photo 12 – LACT**


Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



**Photo 13 – Wildlife Netting in disrepair**

**Photo 14 – Debris and Wildlife Netting in disrepair**

**Inspection Photos**  
**Location Name: Hunt 8-60-17A PAD**  
**Location ID: 457131**



**Photo 15 – Wildlife Netting in disrepair**

**Photo 16 – Unmarked Risers**