

Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 397126

Location Name: Wilson Creek Morrison Unit-63N94W
/34SWSW

Inspection Document #: 702800274

Rio Blanco County, CO

SWSW Section 34 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Wilson Creek Morrison Unit-63N94W /34SWSW

Location ID: 397126



Photo 1. Photos taken from the north of the Location shows an overview of the Location including the well marker.



Photo 2. Photos taken from the south of the Location shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800274

Inspection Photos

Location Name: Wilson Creek Morrison Unit-63N94W /34SWSW

Location ID: 397126



Photo 3. Photos taken from the south of the Location shows soils are compacted and vegetation consists of the annual weeds common dandelion and common stork's-bill.



Photo 4. Photos taken from the southeast of the Location shows reference area vegetation.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800274