

Inspection Photos

API: 071-06399

Operator: OGRIS OPERATING LLC

Inspection Date: 6/2/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 1. Facing southeast at the beginning of the reclaimed access road. The perennial vegetation is progressing well along the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 2. There are noxious weeds (Canada thistle) at the beginning of the reclaimed road that need to be controlled. Lat/Long:37.15916,-104.90602.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 3. There are noxious weeds (Canada thistle) along the first rip/rap drainage.
Lat/Long:37..15779, -104.90445.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 4. Facing south further along the road. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 5. Facing south further along the road. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 6. Facing south at the reclaimed location. The vegetation is not establishing as well at the location and additional hand seeding should be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 7. Facing north at the [GE-73-94](#) location. There are noxious weeds (Scotch thistle) in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022

Inspection Photos



Photo 8. Facing southeast in the canyon bottom toward the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06399 | Date: 6/2/2022