

# Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 397053

Location Name: Wilson Creek Morrison Unit-62N94W  
/2NWNE

Inspection Document #: 702800278

Rio Blanco County, CO

NWNE Section 2 T2N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Morrison Unit-62N94W /2NWNE

Location ID: 397053



**Photo 1.** Photos taken at the well marker shows an overview of the southern portion of the Location. A concrete slab is present and must be removed per 1004 rules.



**Photo 2.** Photos taken from the south of the Location shows evidence of vehicle traffic and a high proportion of bare ground.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800278



## Inspection Photos

Location Name: Wilson Creek Morrison Unit-62N94W /2NWNE

Location ID: 397053



**Photo 3.** Photos taken from the north of the Location shows an overview of the Location and vegetation community.



**Photo 4.** Photos taken from the south of the Location shows the vegetation community consisting of perennial grasses and a high proportion of bare ground, compared to reference areas levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800278



## Inspection Photos

Location Name: Wilson Creek Morrison Unit-62N94W /2NWNE

Location ID: 397053



**Photo 5.** Photos shows bull thistle, a CO State List B Noxious Weed.



**Photo 6.** Photos taken to the northwest of the Location shows reference area vegetation.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800278