

# Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314507

Location Name: Wilson Creek Unit-63N94W /34SESE

Inspection Document #: 702800282

Rio Blanco County, CO

SESE Section 34 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34SESE

Location ID: 314507



**Photo 1.** Photos taken at the west of the Location shows an overview of the Location.



**Photo 2.** Photos taken from the north of the Location shows a small area which appears to have been seeded with perennial grasses.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800282



## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34SESE

Location ID: 314507



**Photo 3.** Photo taken from the southeast of the Location shows an area which may have been previously reclaimed is dominated by undesirable species and weeds, rabbitbrush cheatgrass and field pennycress.



**Photo 4.** Refer to Photo 3 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800282



## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34SESE

Location ID: 314507



**Photo 5.** Photo taken from the south of the Location shows an area which may have been previously reclaimed is dominated by undesirable species and weeds, rabbitbrush and cheatgrass.



**Photo 6.** Photos taken to the southeast of the Location shows reference area vegetation.

Inspection Number: 702800282



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources