

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2022

Submitted Date:

06/04/2022

Document Number:

701103188**FIELD INSPECTION FORM**
 Loc ID 450760 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450749	WELL	PR	08/13/2018	OW	077-10382	Nichols 0994-24-12W	PR
450750	WELL	PR	10/06/2018	OW	077-10383	Nichols Federal 0994-24-20E	PR
450752	WELL	PR	08/14/2018	OW	077-10385	Nichols 0994-24-12E	PR
450753	WELL	PR	09/14/2018	OW	077-10386	Nichols Federal 0994-24-18E	PR
450754	WELL	PR	08/11/2018	OW	077-10387	Nichols 0994-24-11W	PR
450755	WELL	PR	09/15/2018	OW	077-10388	Nichols 0994-24-17W	PR
450756	WELL	PR	10/08/2018	OW	077-10389	Nichols Federal 0994-24-21E	PR
450757	WELL	PR	08/15/2018	OW	077-10390	Nichols 0994-24-10E	PR
450758	WELL	PR	09/11/2018	OW	077-10391	Nichols 0994-24-18W	PR
450759	WELL	PR	09/08/2018	OW	077-10392	Nichols 0994-24-15E	PR
450761	WELL	PR	10/03/2018	OW	077-10393	Nichols Federal 0994-24-19E	PR
450762	WELL	PR	09/11/2018	OW	077-10394	Nichols Federal 0994-24-17E	PR
450763	WELL	PR	08/12/2018	OW	077-10395	Nichols 0994-24-10W	PR
450764	WELL	PR	09/08/2018	OW	077-10396	Nichols 0994-24-13E	PR
450765	WELL	PR	08/13/2018	OW	077-10397	Nichols 0994-24-11E	PR
450766	WELL	PR	10/12/2018	OW	077-10398	Nichols 0994-24-19W	PR
450767	WELL	PR	10/12/2018	OW	077-10399	Nichols 0994-24-21W	PR
450768	WELL	PR	09/21/2020	OW	077-10400	Nichols 0994-24-16E	PR
450769	WELL	PR	10/12/2018	OW	077-10401	Nichols 0994-24-20W	PR

General Comment:

[COGCC Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 19		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 19		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	450749	Type:	WELL	API Number:	077-10382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450750	Type:	WELL	API Number:	077-10383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450752	Type:	WELL	API Number:	077-10385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450753	Type:	WELL	API Number:	077-10386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450754	Type:	WELL	API Number:	077-10387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450755	Type:	WELL	API Number:	077-10388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450756	Type:	WELL	API Number:	077-10389	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450757	Type:	WELL	API Number:	077-10390	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	450758	Type:	WELL	API Number:	077-10391	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450759	Type:	WELL	API Number:	077-10392	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450761	Type:	WELL	API Number:	077-10393	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450762	Type:	WELL	API Number:	077-10394	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450763	Type:	WELL	API Number:	077-10395	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450764	Type:	WELL	API Number:	077-10396	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450765	Type:	WELL	API Number:	077-10397	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	450766	Type:	WELL	API Number:	077-10398	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	450767	Type:	WELL	API Number:	077-10399	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	450768	Type:	WELL	API Number:	077-10400	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	450769	Type:	WELL	API Number:	077-10401	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking		
Ditches						
		Check Dams				
Seeding						
		Ditches				
Berms						
Compaction						
Gravel						
Waddles						
		Culverts				
Check Dams						
		Compaction				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103191	Inspection 701103188 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770748