

# Final Reclamation Inspection

May 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 331555

Inspection Document #: 701900375

SWNW Section 36 T4N R68W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gaddis 12-36  
Location ID: 331555



**Photo 1.** 2021 aerial imagery of the well pad and access road. Note: tank battery highlighted in blue is associated with the Gaddis 22-36 well.

Inspection Photos  
Location Name: Gaddis 12-36  
Location ID: 331555



**Photo 2.** Overview photo of the well pad taken from the eastern edge looking west.



Inspection Photos  
Location Name: Gaddis 12-36  
Location ID: 331555



**Photo 3.** Carindal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Gaddis 12-36  
Location ID: 331555



**Photo 4.** Cardinal overview photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: crop growth within well pad appears consistent with surrounding crop.