

Inspection Photos

May 31, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334901

Location Name: Shideler-66S92W /32SWNE

Inspection Document #: 702800286

Garfield County, CO

SWNE Section 32 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334901



Photo 1. Photo taken from the east of the Location behind the separator shows the previously undermining berm is intact. Photo shows the view from the outside of the berm.



Photo 2. Photo taken from the east of the Location behind the separator shows the previously undermining berm is intact. Photo shows the view from the inside of the berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800286

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334901



Photo 3. Photo taken from the east of the Location shows where erosion was raked. Erosion continues at the site, as no control measures were implemented to stabilize soils.



Photo 4. Refer to Photo 3 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800286

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334901



Photo 5. Photo taken from the north of the Location shows where a gully was raked. Erosion continues at the site, as no control measures were implemented to stabilize soils.



Photo 6. Refer to Photo 5 comment.