

Inspection Photos

May 31, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335228

Location Name: Benzel Disposal-66S93W /36NWNE

Inspection Document #: 702800296

Garfield County, CO

NWNE Section 36 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Benzel Disposal-66S93W /36NWNE
Location ID: 335228



Photo 1. Photo taken from the southwest of the Location shows knapweed which appears to have been treated with herbicide.



Inspection Photos
Location Name: Benzel Disposal-66S93W /36NWNE
Location ID: 335228



Photo 2. Photo taken from the south of the Location shows concrete forms no longer in use and adjacent areas requiring interim reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800296

Inspection Photos

Location Name: Benzel Disposal-66S93W /36NWNE

Location ID: 335228



Photo 3. Photo taken from the east of the Location shows subsidence resulting in dangerous holes.



Photo 4. Refer to Photo 3 comment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800296