

Inspection Photos
Location Name: Park T-P-4 Pad
Location ID: 428521



Photo #1 ECDs

Photo #2 Production Tanks

Inspection Photos
Location Name: Park T-P-4 Pad
Location ID: 428521



Photo #3 Stained soil

Photo #4 Oily Waste

Inspection Photos
Location Name: Park T-P-4 Pad
Location ID: 428521



Photo #5 Oily Waste & Appears to be mechanical conditions

Photo #6 Oily Waste & Appears to be mechanical conditions

Inspection Photos
Location Name: Park T-P-4 Pad
Location ID: 428521



Photo #7 Oily Waste & Appears to be mechanical conditions

Photo #8 Unused Equipment