



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Aerial View of Spill/Release 482164





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Spill/Release area as seen from  
County Road 29. Note the livestock  
in the right side of the photo.

May 5, 2022 12:47:  
+39.8585N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Excavation looking west. Note  
Black Sulfur Creek on the left side  
of the photo and potentially  
impacted fluids in the base of the  
excavation. Livestock can be seen  
in the background of the photo.

May 5, 2022 1:00:  
+39.8583N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





May 5, 2022 12:53  
+39.8581N -108.3  
Rio Blanco C

Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Stockpile of potentially impacted  
material located west of the  
excavation.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Stockpile of potentially impacted material located east of the excavation. Note the livestock in the background of the photo.

May 5, 2022 1:01:  
+39.8584N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

**Black Sulfur Creek flowing adjacent  
to the Spill/Release area.**

May 5, 2022 12:52:  
+39.8581N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

**Black Sulfur Creek flowing adjacent  
to the Spill/Release area.**

May 5, 2022 12:50:30  
+39.8583N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





**Inspection Photos**

**Spill/Release Name:**

**4-inch flex-pipe produced water line**

**Spill/Release ID: 482164**

**Inspection Date: May 5, 2022**

**Apparent visible sheen on Black  
Sulfur Creek adjacent to the  
Spill/Release area.**

May 5, 2022 12:51:  
+39.8582N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





May 5, 2022 12:56  
+39.8577N -108.3  
Rio Blanco C

Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Apparent visible sheen on Black  
Sulfur Creek adjacent to the  
Spill/Release area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





May 5, 2022 12:52  
+39.8581N -108.3  
Rio Blanco C

Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Up-gradient photo of Black Sulfur  
Creek. Note the lack of a visible  
sheen on the surface.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Down-gradient photo of Black  
Sulfur Creek. Note the lack of a  
visible sheen on the surface.

May 5, 2022 1:02:  
+39.8583N -108.3  
Rio Blanco C



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources





Inspection Photos  
Spill/Release Name:  
4-inch flex-pipe produced water line  
Spill/Release ID: 482164  
Inspection Date: May 5, 2022

Spill/Release area as seen from  
where Black Sulfur Creek passes  
under County Road 29.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources