

Inspection Photos
Location Name: Cody 2
Location ID: 324595



Photo 1. Overview of location taken facing east.



Photo 2. Erosion on access road. Hardhat for scale.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Cody 2
Location ID: 324595



Photo 3. Erosion on access road. Hardhat for scale.



Photo 4. Erosion on access road. Hardhat for scale.

