

Inspection Photos
Location Name: Dwinell 3-A
Location ID: 324666



Photo 1. Overview of wellhead portion of location taken facing east.



Photo 2. Firewood debris on location.



Inspection Photos
Location Name: Dwinell 3-A
Location ID: 324666



Photo 3. Firewood and fire remains on location.



Photo 4. Close-up of photo 3, firewood and fire remains.

