

Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Facility ID: 149002

Facility Name: Wilson Creek Landfarm

Inspection Document #: 702800267

Rio Blanco County, CO

NENW Section 35 T3N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Facility Name: Wilson Creek Landfarm
Facility ID: 149002



Photo 1. Photo taken from the south of the Location shows an overview to the east. Final Reclamation has not been initiated and the Location is being used as a storage yard.



Photo 2. Photo taken from the south of the Location shows an overview to the west.



Inspection Photos
Facility Name: Wilson Creek Landfarm
Facility ID: 149002



Photo 3. Photo taken from the west of the Location shows storage of chemical tanks.



Photo 4. Photo taken from the west of the Location shows a secondary containment tank lacks control measures to allow for wildlife egress.



Inspection Photos
Facility Name: Wilson Creek Landfarm
Facility ID: 149002



Photo 5. Photo taken from the east of the Location shows the CO List B Noxious Weeds houndstongue (left) and Canada thistle (right).

