

# Inspection Photos

API: 055-06186

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** Facing east along the former access road. Perennial vegetation cover has not established. There is Scotch thistle noxious weeds along the former road which needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 2.** Facing northeast along the former road. The desirable vegetation has not re-established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 3.** Facing northeast toward the location. The desirable vegetation has not re-established at the location and there are noxious weeds including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 4.** Facing northwest at the east side of the location. The desirable vegetation has not re-established at the location and there are noxious weeds including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 5.** Facing west toward the location. The desirable vegetation has not re-established at the location and there are noxious weeds including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 6.** Drone aerial photo facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022

## Inspection Photos



**Photo 7.** 2015 aerial image of the location shows the disturbance area of the location and pit. All associated disturbances must be reclaimed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022



## Inspection Photos



**Photo 8.** Facing southeast at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Sand drop seed, among other native species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06186 | Date: 6/7/2022