

Inspection Photos

API: 055-06279

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the location. There is desirable vegetation cover throughout most of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing northeast at the southeast side of location. There are some Scotch thistle noxious weeds that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06279 | Date: 6/7/2022