

# Inspection Photos

API: 055-06195

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06195 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** Facing southwest toward the location. The desirable vegetation has not reestablished at the location and there are noxious weeds including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06195 | Date: 6/7/2022



## Inspection Photos



**Photo 2.** Facing southeast toward the location. The desirable vegetation has not reestablished at the location and there are noxious weeds including Red stem filaree, Field bindweed, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/7/2022



## Inspection Photos



**Photo 3.** Facing toward the west side of the location. It appears weed control was performed in this area. The location will need to be reseeded to establish desirable vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/7/2022



## Inspection Photos



**Photo 4.** Facing southwest at the surrounding undisturbed vegetation which consists of Western wheat, Needle and thread grass, Sand drop seed, among other native species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06195 | Date: 6/7/2022