

Inspection Photos

API: 055-06201

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the former access road. It appears weed control was performed due to bare ground. There are still noxious weeds present including Field bindweed, Red stem filaree, and Jointed goatgrass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing west at the location. It appears weed control was performed due to bare ground. There are still noxious weeds present including Field bindweed, Red stem filaree, and Jointed goatgrass. Noxious weeds need to be controlled and the location reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/7/2022

Inspection Photos



Photo 3. Facing east at the location. It appears weed control was performed due to bare ground. There are still noxious weeds present including Field bindweed, Red stem filaree, and Jointed goatgrass. Noxious weeds need to be controlled and the location reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/7/2022

Inspection Photos



Photo 4. There is still some Jointed goat grass found on location that needs to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/7/2022

Inspection Photos



Photo 5. Facing west toward the surrounding undisturbed reference area which consists of desirable vegetation Western wheat grass, Smooth brome among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06201 | Date: 6/7/2022