

Inspection Photos and Issue Report

6/07/2022

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312733

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312733



Photo 1: Photos taken from the Location, facing south. Photos show Location has not been recontoured/regraded; cut slopes evident. Reclamation of the Location has not been completed in accordance with 1004 requirements.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312733



Photo 2: Photos show Location has not been recontoured/regraded; cut slopes evident. Reclamation of the Location has not been completed in accordance with 1004 requirements.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312733



Photo 3: Photo shows Operator did not remove gravel/base material from the Location, but rather mixed it with the soils, this does not comport with 1002.c and 1004.a (1003.e.(2)), as soils did not remain properly segregated, and horizons were not replaced to their original relative positions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312733



Photo 4: Photos show reclamation of the access road has not been completed; gravel has not been removed, road has not been decompacted and reclaimed.