

Inspection Photos

API: 055-06101

Operator: MANZANO LLC

Inspection Date: 6/7/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 1. Drone aerial photo facing southwest along the access road. A pipe riser remains at the red arrow. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 2. Drone aerial photo facing southwest along the access road. There is erosion occurring along the road which has not been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 3. Drone aerial photo facing northwest along the access road. The access road has not been recontored and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 4. Drone aerial photo facing northwest shows the location has not been recontoured and reclaimed. The location disturbance is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 5. The pipeline risers still remain at the location shown at red arrows. Pipeline riser should have been abandoned per 1100 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 6. Facing southwest overlooking the location. There are multiple areas of significant gully erosion along the cut and fill slopes shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022

Inspection Photos



Photo 7. The pit was never backfilled and reclaimed. This photo shows the significant erosion along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 6/7/2022