

**CHEVRON USA INC - 16700**  
**API# 05-103-07022 HAGOOD, L.N. #A-9X**  
**Inspection Date : 6/8/2022**



Injection wellhead during MIT

**Click here to read the form**  
**Oil and Gas Wellhead Integrity Test**  
**Form 21**

**Wellhead Integrity Test**  
 This form is to be completed by the operator of the wellhead. It is to be used to document the results of the test and to provide information to the regulatory agency.

**Wellhead Information**  
 Wellhead ID: 6315-6459  
 Wellhead Name: 6315-6459  
 Wellhead Type: 6315-6459  
 Wellhead Location: 6315-6459

**Test Information**  
 Test Type: MIT  
 Test Date: 6-8-2022  
 Test Time: 08:22  
 Test Results: 1250

**Signatures**  
 Operator: [Signature]  
 Inspector: [Signature]  
 Date: 6-8-2022

Form 21 field copy