

Inspection Photos
Location Name: Trupp 8-16
Location ID: 320039



Pic 1 pump jack/wellhead



Pic 2 gas meter run, separator

Inspection Photos
Location Name: Trupp 8-16
Location ID: 320039



Pic 3 tanks, no sign on battery



Pic 4 riser on location has mechanical issue / stained soil needs to be removed