

Inspection Photos
Location Name: Hearther 2-28
Location ID: 319758

Jun 8, 2022 at 3:20:24 PM
39.844040,-104.324727
Adams County
COGCC



Pic 1 wellhead / pum jack

Jun 8, 2022 at 3:20:35 PM
39.844040,-104.324727
Adams County
COGCC



Pic 2 storage of equipment

Inspection Photos
Location Name: Hearther 2-28
Location ID: 319758

Jun 8, 2022 at 3:20:54 PM
39.844040,-104.324727
Adams County
COGCC



Jun 8, 2022 at 3:21:04 PM
39.843949,-104.324665
Adams County
COGCC



Pic 3 storage of equipment / trash

Pic 4 storage of equipment / trash

Inspection Photos
Location Name: Hearther 2-28
Location ID: 319758

Jun 8, 2022 at 3:21:22 PM
39.843752,-104.324810
Adams County
COGCC



Pic 5 storage of equipment / trash

Jun 8, 2022 at 3:21:50 PM
39.843752,-104.324810
Adams County
COGCC



Pic 6 storage of equipment / trash

Inspection Photos
Location Name: Hearther 2-28
Location ID: 319758

Jun 8, 2022 at 3:21:58 PM
39.843752,-104.324810
Adams County
COGCC



Pic 7 storage of equipment / trash

Jun 8, 2022 at 3:33:40 PM
39.842901,-104.321026
Adams County
COGCC



Pic 8 separator

Inspection Photos
Location Name: Hearther 2-28
Location ID: 319758

Jun 8, 2022 at 3:34:01 PM
39.842901,-104.321026
Adams County
COGCC



Pic 9 risers and hole in ground

Jun 8, 2022 at 3:34:47 PM
39.842772,-104.320942
Adams County
COGCC



Pic 10 Tanks