

Inspection Photos
Location Name: UPRR Walker 1-29
Location ID: 319751

Jun 8, 2022 at 3:43:39 PM
39.844324,-104.342622
Adams County
COGCC



Pic 1 wellhead, pump jack is leaning forward bending rods, may cause issue of parted rods / release in the future

Jun 8, 2022 at 3:47:12 PM
39.846059,-104.339248
Adams County
COGCC



Pic 2 separator

Inspection Photos

Location Name: UPRR Walker 1-29

Location ID: 319751



Pic 3 tanks, berms need maintenance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources