

Inspection Photos

API: 071-07064

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07064 | Date: 6/10/2022

Inspection Photos



Photo 1. Facing south near the creek crossing along the main road. There are noxious weeds (Scotch thistle) in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07064 | Date: 6/10/2022

Inspection Photos



Photo 2. Facing southwest at the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07064 | Date: 6/10/2022