

Inspection Photos

API: 071-07041

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 6/10/2022

Inspection Photos



Photo 1. Facing west near the creek crossing along the main road. There are noxious weeds (Scotch thistle) in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 6/10/2022

Inspection Photos



Photo 2. Facing east at the creek crossing along the access road. There are noxious weeds (Scotch thistle) in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 6/10/2022

Inspection Photos



Photo 3. Facing east at the creek crossing along the access road. There are noxious weeds (Scotch thistle) in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 6/10/2022

Inspection Photos



Photo 4. Facing northeast at the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07041 | Date: 6/10/2022