

Inspection Photos

API: 071-08082

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 1. Facing northeast along the main road . This area along the road has been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 2. Facing southwest toward the access road. The erosion along the access road has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 3. There are rock check dams installed along the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 4. Further up the access road. A new culvert has been installed along the road to divert stormwater.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 5. Facing southwest along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08082 | Date: 6/10/2022