

# Inspection Photos

API: 071-08083

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 1.** Facing southeast along the main access road. The road has been regraded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 2.** Facing southeast along the main access road. The road has been regraded and stabilized. Areas of disturbance are seeded and hydromulched.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 3.** Facing south along the main road. A new culvert has been installed and the crossing is repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 4.** Facing south further along the main road. A new culvert has been installed and the crossing is repaired. A new flowline riser has been installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 5.** Facing south further along the main road. A new culvert has been installed and the crossing is repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022

## Inspection Photos



**Photo 6.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08083 | Date: 6/10/2022