

Inspection Photos

June 8, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313147

Location Name: Walker 7-93-12 /Pad4

Inspection Document #: 702800313

Moffat County, CO

NENE Section 12 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Walker 7-93-12 /Pad4
Location ID: 313147



Photo 1. Photo taken from the center of the pad shows the area around the wellhead.



Photo 2. Photo taken from the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800313

Inspection Photos

Location Name: Walker 7-93-12 /Pad4

Location ID: 313147



Photo 3. Photo taken from the north of the Location shows perennial pepperweed, a noxious weed.



Photo 4. Photo taken from the east of the Location shows Russian knapweed, a noxious weed. Photo also shows a marked anchor which must be removed for final reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800313

Inspection Photos
Location Name: Walker 7-93-12 /Pad4
Location ID: 313147



Photo 5. Photo taken from the north of the Location shows Scotch thistle a noxious weed.




Photo 6. Photo taken from the north of the Location shows Canada thistle a noxious weed.



Inspection Photos
Location Name: Walker 7-93-12 /Pad4
Location ID: 313147



Photo 7. Photo taken from the west of the Location shows two risers which need to be removed for final reclamation.



Photo 8. Photo taken from the east of the Location shows a power line which needs to be removed for final reclamation.



Inspection Photos
Location Name: Walker 7-93-12 /Pad4
Location ID: 313147



Photo 9. Photo taken from the center of the Location shows highly compacted soils.



Photo 10. Photo taken from the southwest of the Location shows the contour of the pad does not match the surrounding landscape.

Inspection Photos
Location Name: Walker 7-93-12 /Pad4
Location ID: 313147



Photo 11. Photo taken from the southwest of the Location shows adjacent reference area vegetation.



Photo 12. Photo taken from the southeast of the Location shows adjacent reference area vegetation.