



99999999

# OIL AND GAS CONSERVATION COM

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100



00511410

FEB 22 1995

## FIELD INSPECTION FORM

API No. 05- <u>017 - 06358</u>		LEASE NAME: <u>UPRR558 Amoco</u> #1	
LOCATION: <u>S65W17-125-44W</u>		OPERATOR: <u>Amoco Prod.</u>	
DATE: <u>1-31-95</u>		INSPECTOR: <u>R. VanSickle</u>	
Inspection Type:	Inspection Status: <u>TA</u>	PA:	Pass/Fail:

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs	<u>IN PLACE.</u>	<input checked="" type="checkbox"/>
Pits (Reserve/Production)	<u>NONE.</u>	<input checked="" type="checkbox"/>
Fences	<u>—</u>	<input type="checkbox"/>
Tank Battery Equipment	<u>ALL EQUIPMENT REMOVED.</u>	<input checked="" type="checkbox"/>
Fire Walls/Berms/Dikes		<input type="checkbox"/>
General Housekeeping	<u>GOOD.</u>	<input checked="" type="checkbox"/>
Spills (Oil/Water)		<input type="checkbox"/>
Bradenhead		<input type="checkbox"/>
Drilling Well/Workover		<input type="checkbox"/>
Surface Rehabilitation		<input type="checkbox"/>
Miscellaneous	<u>TBS IN HOLE &amp; MASTER VALVE &amp; 2" BULL PLUG ON TOP WELL HEAD GUARD AROUND WELL.</u>	<input checked="" type="checkbox"/>

### CORRECTIVE ACTION REQUIRED:

NEEDS MIT OR PLUG.

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.