

# Inspection Photos

API: 071-08095

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 1.** Facing east at the drainage crossing. This area was damage in the flood event where exposed pipe lines were observed. This area has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 2.** There is rock rip rap installed below the culvert outlets. Noxious weeds are beginning to sprout up in this area and will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 3.** Further along the road at this drainage. The culvert has been repaired. It appears work is still in process for stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 4.** Facing northwest along the road. The rock dams will need to be repaired in this area. The machinery is staged near the top of the hill.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 5.** Facing west toward the well site. The road and culvert have been repaired at this drainage area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022

## Inspection Photos



**Photo 6.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08095 | Date: 6/10/2022