

# Inspection Photos

June 8, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313326

Location Name: Amelia-67N93W /1SESE

Inspection Document #: 702800320

Moffat County, CO

SESE Section 1 T7N R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 1.** Photo taken from the south of the Location shows an overview of the Location.



**Photo 2.** Photo taken from the south of the Location shows a pile of stone which must be removed for final reclamation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800320

Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 3.** Photo taken from the northwest of the Location shows a power line to the south which must be removed for final reclamation. Photo also shows the contour of the pad does not match the surrounding landscape.



**Photo 4.** Photo taken from the south of the Location shows a riser which will need to be removed for final reclamation. Also note dense cover of whitetop, a noxious weed.



Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 5.** Photo taken from the south of the Location shows a patch of Canada thistle, a noxious weed.



**Photo 6.** Photo taken from the south of the Location shows a patch of whitetop and a scotch thistle, both noxious weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800320

Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 7.** Photo taken from the north of the Location shows interim areas with poor vegetation cover due to highly compacted soils.



**Photo 8.** Photo taken from the north of the Location shows interim areas with highly compacted soils.



Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 9.** Photo taken from the north of the Location shows areas seeded with smooth brome, a nonnative species not found in the adjacent reference areas.



Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 10.** Photo taken from the northwest of the Location shows the contour of the Location does not match the adjacent areas. The cut slope (red circle) remains. There are also several berms and /or soil piles on Location (red arrows).



Inspection Photos  
Location Name: Amelia-67N93W /1SESE  
Location ID: 313326



**Photo 11.** Photo taken from the north of the Location shows adjacent reference area vegetation.



**Photo 12.** Photo taken from the south of the Location shows adjacent reference area vegetation.

