

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 318928

Inspection Document #: 697503995

Weld County, CO

NENE Section 18 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SERAFINI GAS UNIT #1
Location ID: 318928



Photo 1. Photo taken from the western location, facing South. Photo illustrates the location has been planted. There appears to be large cobble/rock that doesn't appear to be similar to reference areas.



Photo 2. Photo taken from the western location, facing Southeast. See comments under Photo 1.

Red circle identifies a City of Longmont monitoring well.

Inspection Photos
Location Name: SERAFINI GAS UNIT #1
Location ID: 318928



Photo 3. Photo taken from the western location, facing East.
See comments under Photo 1.



Photo 4. Photo taken from the western location, facing North.
See comments under Photo 1.