

TEP
O'Toole
Location # 335541



location



location

TEP
O'Toole
Location # 335541



location



location



TEP
O'Toole
Location # 335541



Debris



Wild life ramp

TEP
O'Toole
Location # 335541



Photo from previous inspection



Lack of stabilization (photo from recent inspection)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
O'Toole
Location # 335541



Lack of stabilization



Lack of stabilization



TEP
O'Toole
Location # 335541



Lack of stabilization



Lack of stabilization



TEP
O'Toole
Location # 335541



Lack of stabilization



Lack of stabilization/ Debris



TEP
O'Toole
Location # 335541



Lack of stabilization




Lack of stabilization

TEP
O'Toole
Location # 335541



Debris



Debris

TEP
O'Toole
Location # 335541



Debris



Staining

TEP
O'Toole
Location # 335541



Staining



Debris old waddle buried from slope erosion



TEP
O'Toole
Location # 335541



Waddles butt together not overlapped



Label with different operator

TEP
O'Toole
Location # 335541



Label falling off of tank



Lack of stabilization on access road



TEP
O'Toole
Location # 335541



Check dam not working on access road



Check dam not working on access road

TEP
O'Toole
Location # 335541



Check dam not working on access road



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources