

Inspection Photos

June 10, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313347

Location Name: Antietam-67N93W /12NWNW

Inspection Document #: 702800325

Moffat County, CO

NWNW Section 12 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Antietam-67N93W /12NWNW

Location ID: 313347



Photo 1. Photo taken from the northwest of the Location. Vegetation is dominated by noxious and undesirable species. Weeds were recently sprayed, although some were missed in treated areas and other areas were not treated at all. Seeded plant species are rare.



Photo 2. Photo taken from the northeast of the Location shows platy soil structure indicating compacted soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800325

Inspection Photos
Location Name: Antietam-67N93W /12NWNW
Location ID: 313347



Photo 3. Photo taken from the northeast of the Location shows a stormwater BMP/berm which has not been removed and recountoured. Note untreated noxious weeds (red circles).



Inspection Photos
Location Name: Antietam-67N93W /12NWNW
Location ID: 313347



Photo 4. Photo taken from the west of the Location shows the vegetation community. Note the almost complete lack of seeded species (red circles). Seeded species are non-native, and do not match the adjacent native reference areas.



Photo 5. Photo taken from the south of the Location shows the access road, which needs to be reclaimed for final reclamation.

Inspection Photos
Location Name: Antietam-67N93W /12NWNW
Location ID: 313347



Photo 6. Photo taken from the previously reclaimed area at the north of the Location shows establishment of sparse seeded species and dominance of noxious and undesirable species. Weeds in this area have not been treated. Seeded species are non-native, and do not match the adjacent native reference areas.



Photo 7. Photo taken from the previously reclaimed area at the north of the Location shows an area with no establishment of seeded species and dominance of noxious and undesirable species. Weeds in this area have not been treated.

Inspection Photos
Location Name: Antietam-67N93W /12NWNW
Location ID: 313347



Photo 8. Photo taken from the east of the Location shows the reference area vegetation community is native rangeland. Note weed debris from the Location is impacting adjacent areas.



Inspection Photos
Location Name: Antietam-67N93W /12NWNW
Location ID: 313347



Photo 9. Photos taken from west of the Location across the road shows a pipeline riser which must be removed for final reclamation. Pipeline signage reads “Silver Stream Pipeline Company LLC” and “Pioneer Natural Resources USA Inc.”



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702800325