

Inspection Photos

June 10, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313329

Location Name: Trenton Federal-67N93W /2SESE

Inspection Document #: 702800327

Moffat County, CO

SESE Section 2 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Trenton Federal-67N93W /2SESE

Location ID: 313329



Photo 1. Photo taken from the north of the Location shows an overview of the Location which is almost completely bare ground and noxious weeds (Scotch thistle). Weeds were recently treated although some appear to remain untreated.



Photo 2. Photo taken from the east of the Location shows the access road, which must be reclaimed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800327

Inspection Photos

Location Name: Trenton Federal-67N93W /2SESE

Location ID: 313329



Photo 3. Photo taken from the south of the Location shows seeding has failed. Photo also shows the seedbed/soil surface appears to have been graded smooth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800327

Inspection Photos
Location Name: Trenton Federal-67N93W /2SESE
Location ID: 313329



Photo 4. Photo taken from the east of the Location shows platy soil structure indicating compacted soils. Soils were very firm and penetration below approximately 2 inches was very difficult compared to adjacent undisturbed areas.



Photo 5. Refer to Photo 4 comments.

Inspection Photos
Location Name: Trenton Federal-67N93W /2SESE
Location ID: 313329



Photo 6. Photo taken from the west of the Location shows noxious weeds which appear to have been missed during the recent treatment.



Inspection Photos
Location Name: Trenton Federal-67N93W /2SESE
Location ID: 313329



Photo 7. Photo taken from the south of the Location shows a stormwater BMP which has not been removed.



Photo 8. Refer to Photo 7 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800327

Inspection Photos
Location Name: Trenton Federal-67N93W /2SESE
Location ID: 313329



Photo 9. Photo taken from the south of the Location shows the reference area vegetation community is native rangeland. Note also the power line remaining just off Location.

