

Inspection Photos
Location Name: Vetter 1-15A
Location ID: 320323



Pic 1 stained soil by wellhead needs to be removed.



Pic 2 pump jack / wellhead / electric equipment

Inspection Photos
Location Name: Vetter 1-15A
Location ID: 320323

Jun 13, 2022 at 1:50:59 PM
39.872475,-104.306768
Adams County
COGCC



Pic 3 separator

Jun 13, 2022 at 1:51:36 PM
39.872195,-104.307399
Adams County
COGCC



Pic 4 tanks

