

**Inspection Photos**  
**Location Name: Comanche Creek 3-14**  
**Location ID: 320502**



**Pic 1 wellhead, bradenhead is not plumbed to surface, stained soil, weeds unmanaged**



**Pic 2 trash on location, weeds unmanaged**





## Inspection Photos

Location Name: Comanche Creek 3-14

Location ID: 320502



**Pic 3 unused equipment on location needs to be removed**



**Pic 4 tanks needs to be removed**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Comanche Creek 3-14**  
**Location ID: 320502**



**Pic 5 trash on location**



**Pic 6 stained soil in motor house needs to be removed**



## Inspection Photos

Location Name: Comanche Creek 3-14

Location ID: 320502



**Pic 7 horses head is not connected to pump jack rods sticking out of well.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources