

Inspection Photos

Location Name: Robbins 24-11A

Location ID: 319995



Pic 1 risers, weeds unmanaged



Pic 2 riser



Inspection Photos
Location Name: Robbins 24-11A
Location ID: 319995



Pic 3 tanks weeds unmanaged



Pic 4 separator

Inspection Photos
Location Name: Robbins 24-11A
Location ID: 319995



Pic 5 wellhead fence around pumpjack needs repair, motor house needs repair



Pic 6 fence around pump jack needs repair

Inspection Photos
Location Name: Robbins 24-11A
Location ID: 319995



Pic 7 Motor house needs repair



Pic 8 motor house needs repair



Inspection Photos
Location Name: Robbins 24-11A
Location ID: 319995



Pic 9 tanks

