

Inspection Photos

Location Name: Gretchen Raglund 2-14

Location ID: 320322



Pic 1 equipment on location needs to be removed, well is PA, unable to access due to gate that is barb wired shut



Pic 2 gate is barb wired shut