

# Inspection Photos

June 10, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313328

Location Name: Boston Federal-67N93W /2NWSE

Inspection Document #: 702800330

Moffat County, CO

NWSE Section 2 T7N R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Boston Federal-67N93W /2NWSE  
Location ID: 313328



6/10/22  
+40.584996,-107.798000  
144° SE

**Photo 1.** Photo taken from the north of the Location shows an overview of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800330



Inspection Photos  
Location Name: Boston Federal-67N93W /2NWSE  
Location ID: 313328



**Photo 2.** Photo taken from the northeast of the Location shows an off Location flowline riser which must be removed and reclaimed.



**Photo 3.** Photo taken from the northeast of the Location shows the access road, which must be reclaimed. Note also the power line remaining just off Location which must be removed and reclaimed.



## Inspection Photos

Location Name: Boston Federal-67N93W /2NWSE

Location ID: 313328



**Photo 4.** Photo taken at the south of the Location shows platy soil structure indicating compacted soils. Soils were firm compared to adjacent undisturbed areas.



**Photo 5.** Photo taken to the south of the Location in adjacent undisturbed areas shows loose, granular and subangular blocky soil structures.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800330



## Inspection Photos

Location Name: Boston Federal-67N93W /2NWSE

Location ID: 313328



**Photo 6.** Photo taken from the west of the Location shows some establishment of perennial plants (western wheatgrass, sagebrush) and dense cover of the noxious weed, cheatgrass.



**Photo 7.** Photo taken from the south of the Location shows the majority of the Location without any perennial plants. Vegetation is dominated by desert madwort (annual undesirable species), cheatgrass and Scotch thistle (noxious weeds).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800330



## Inspection Photos

Location Name: Boston Federal-67N93W /2NWSE

Location ID: 313328



**Photo 8.** Photo taken from the south of the Location shows an area which is almost completely bare of vegetation.



**Photo 9.** Photo taken from the east of the Location shows an area which is dominated by the undesirable plant species/weed Russian thistle and bare ground.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800330



Inspection Photos  
Location Name: Boston Federal-67N93W /2NWSE  
Location ID: 313328



**Photo 10.** Photo taken from the south of the Location shows a stormwater BMP which has not been removed.





Inspection Photos  
Location Name: Boston Federal-67N93W /2NWSE  
Location ID: 313328



**Photo 11.** Photo taken from the south of the Location shows the reference area vegetation community is native rangeland.

