

Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 6/14/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022

Inspection Photos



Photo 1. Facing west toward the access road ascending the hillside. The road has been graded. The culvert inlet cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022

Inspection Photos



Photo 2. The culvert outlet has been repaired and rock rip/rap outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022

Inspection Photos



Photo 3. There are noxious weeds along the access road that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022

Inspection Photos



Photo 5. There are noxious weeds Hounds tongue which has not been controlled. The noxious weeds have already produced seed so the weeds will now need to be bagged and removed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07915 | Date: 6/14/2022