

Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 6/14/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022

Inspection Photos



Photo 1. Facing southwest along the main road near the well site. The road has been graded. The culvert inlet is cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022

Inspection Photos



Photo 2. The culvert outlet has been repaired and rock rip/rap outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022

Inspection Photos



Photo 3. Facing toward the northeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022

Inspection Photos



Photo 4. Facing toward the northeast side of the location. This area has been reseeded and rock rip/rap was installed in the erosion channel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022

Inspection Photos



Photo 5. Facing toward the northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 6/14/2022