

Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981



Photo #1 Tanks.



Photo #2 Produced water vault.

Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981



Photo #3 Load off line missing bullplug.



Photo #4 Separator.

Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981



Photo # 5 Pump Jack.



Photo #6 A Stained soil around pump jack.



Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981




Photo #7 tained soil around pump jack




Photo #8 Stained soil around pump jack.



Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981



Photo #9 Unmarked guide line anchor.



Photo #10 Unmarked guide line anchor.

Inspection Photos
Location Name: UPRR 23 PAN AM UT D#4
Location ID: 319981



Photo #11 Unmarked guide line anchor.