

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #1 Crude Tanks.



Photo #2 Produced water tank.

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #3 produced water tank berm.



Photo #4 produced water tank berm.



Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #5 produced water pit 1



Photo #6 produced water pit 1 berm.

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #7 produced water pit 2.



Photo #8 produced water pit 2 berm.

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #9 produced water pit 3



Photo #10 produced water pit 3 berm

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #11 produced water pit 3 berm.



Photo #12 produced water pit 3 berm.



Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #13 Separator.



Photo #14 unmarked tank.

Inspection Photos
Location Name: Badger Oil #1
Location ID: 320339



Photo #15 Pump Jack.